

Under Review Notification

Raised By: Ketan Tailor

Product #: RBE1120-31502W1

Date: August 22, 2019

Product Name: Press In / Push Out Device

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBE1120-31502W1-1	RBE1120-31502W1 REV. 1	Y	Y	N	Y	Y	N	N	19-870	Modify internal diameter of 1.345
RBE1120-31502W1-3	RBE1120-31502W1 REV. 1	Y	Y	N	Y	Y	N	N	19-870	Modify internal diameter of 1.345

Description of Issue:

Part does not fit over tail rotor drive shaft. Internal diameter dimension is too small. See CAR 19-332

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene